

MATERIAL SAFETY DATA SHEET

FOR COATINGS, RESINS AND RELATED MATERIALS

(Approved by U.S. Department of Labor "Essentially Similar" to Form OSHA-20)

Section I

MANUFACTURER'S NAME

DATE OF PREP

1-28-87

U. S. Paint, Div. of Grow Group, Inc.

CITY, STATE, AND ZIP CODE

831 S. 21st Street EMERGENCY TELEPHONE NO (314) 621-0525

St. Louis, MO. 63103

(314) 621-0525

Ğ9207

PRODUCT CLASS

INFORMATION TELEPHONE NO.

Powder

MANUFACTURERS CODE IDENTIFICATION

TRADE NAME

GOLD MET. POWDER

Section II—HAZARDOUS INGREDIENTS

INGREDIENT	CAS NO.	PERCENT	OCCUPATIONAL EXPOSURE LIMITS	VAPOR PRESSURE	TOXICITY DATA
COPPER	7440-50-8		TLV-TWA		TLV-STEL 2 MG/M ³
ZING	7440-66-6		TLV-TWA		Z MOJM
	7 *************************************		5 MG/M ³		

Section III—PHYSICAL DATA								
BOILING RANGE	CU - APPROX	0		VAPOR DENSITY N/	A DHEA	VIER.	CLIGHTER, TH	AN AIR
EVAPORATION RATE	FASTER DSLOWE	R, THAN ETHER	N/A	PERCENT VOLATILE BY VOLUME	N/A	WEIGHT PER GALLON	N/A	
	Se	ction IV—	FIRE AND EXP	LOSION HAZ	ZARD	DATA		
FLAMMABILITY CLA	SSIFICATION	OSHA		FLASH POINT	N/	'A	LEL	N/A

EXTINGUISHING MEDIA

E FOAM

"ALCOHOL" FOAM

Øco₂

E DRY CHEMICAL WATER

□OTHER

UNUSUAL FIRE AND EXPLOSION HAZARDS

Do not expose to spark or open flame.

Section V—HEALTH HAZARD DATA

EFFECTS OF OVEREXPOSURE

COPPER METAL IS SLIGHTLY TOXIC. DUST IRRITATES NOSE AND TRACHEA. GASTRO-ENTERIC SYMPTOMS WITH VOMITING AND INFLAMMATION BY INHALATION OF DUST. METAL FUME FEVER, DERMATITIS BY EXPOSURE. EFFECT IS TEMPORARY. CHRONIC TOXICITY IS CONFINED TO THOSE PERSONS SUFFERING FROM WILSON'S DISEASE.

EMERGENCY AND FIRST AIC PROCEDURES

REMOVE FROM EXPOSURE IMMEDIATELY AND ALLOW TO REST.

Section VI—REACTIVITY DATA

STABILITY DUNSTABLE STABLE

CONDITIONS TO AVOID

Excess heat

INCOMPATABILITY (Materials to avoid) OXIDIZING ACIDS AND OTHER COPPER REACTIVE AGENTS HAZARDOUS DECOMPOSITION PRODUCTS

MINERAL ACID DECOMPOSITION YIELDS HYDROGEN AND TOXIC COPPER COMPOUNDS.

HAZARDOUS POLYMERIZATION I MAY OCCUR SWILL NOT OCCUR

Section VII—SPILL OR LEAK PROCEDURES

STEPS TO BE TAKEN IN CASE MATERIAL IS RELEASED OR SPILLED

SWEEP GENTLY TO AVOID DUST CLOUD FORMATION. WEAR SAFETY GOGGLES WITH SIDE SHIELDS. DUST MASK, AND GLOVES.

WASTE DISPOSAL METHOD

DISPOSE OF IN ACCORDANCE WITH LOCAL, STATE, AND FEDERAL REGULATIONS.

Section VIII—SPECIAL PROTECTION INFORMATION

NIOSH/MSHA approved dust mask. RESPIRATORY PROTECTION

USE ONLY IN OPEN, VENTILATED AREAS.

VENTILATION SUFFICIENT VENTILATION, IN VOLUME AND PATTERN, SHOULD BE PROVIDED TO KEEP AIR CONTAMINATION BELOW CURRENT APPLICABLE OSHA PERMISSIBLE LIMITS.

PROTECTIVE GLOVES REQUIRED FOR THOSE WITH

OTHER PROTECTIVE EQUIPMENT

EYE PROTECTION EXTREME SENSITIVITY

COVERALLS, PROTECTIVE CREAM ON EXPOSED SKIN

SURFACES


WEAR SAFETY GOGGLES WITH SIDE SHIELDS

Section IX—SPECIAL PRECAUTIONS

PRECAUTIONS TO BE TAKEN IN HANDLING AND STORING

OTHER PRECAUTIONS

DO NOT TAKE INTERNALLY



MATERIAL SAFETY DATA SHEET

FOR COATINGS, RESINS AND RELATED MATERIALS

(Approved by U.S. Department of Labor "Essentially Similar" to Form OSHA-20)

Section I

MANUFACTURER'S NAME

DATE OF PREP

1-28-87

U. S. Paint, Div. of Grow Group, Inc.

CITY, STATE, AND ZIP CODE

St. Louis, MO. 63103

831 S. 21st Street EMERGENCY TELEPHONE NO

(314) 621-0525

PRODUCT CLASS

INFORMATION TELEPHONE NO.

(314) 621-0525

Powder

TRADE NAME

MANUFACTURERS CODE IDENTIFICATION

Ğ9207

GOLD MET. POWDER

Section II—HAZARDOUS INGREDIENTS

INGREDIENT		CAS NO.	CAS NO. PERCENT		VAPOR PRESSURE	TOXICITY DATA	
COPPER	••	7 440 - 50 - 8		TLV-TWA 1 MG/M ³		TLV-STEL 2 MG/M ³	
ZINC		7440-66-6		TLV-TWA 5 MG/M ³			

Section III—PHYSICAL DATA						
BOILING RANGE	CU - APPROX. 2300 C ZN - APPROX. 950 C		VAPOR DENSITY N/	A DHEA	VIER.	LIGHTER, THAN AIR
EVAPORATION RATE	FASTER SLOWER, THAN ETHER	N/A	PERCENT VOLATILE BY VOLUME	N/A	WEIGHT PER GALLON	N/A
	Section IV—F	IRE AND E	XPLOSION HAZ	ZARD	DATA	
FLAMMABILITY CLA	SSIFICATION OSHA		FLASH POINT	N/	'A	LEL N/A

EXTINGUISHING MEDIA

E FOAM

O"ALCOHOL"

⊠co⁵

DAY CHEMICAL SWATER FOG

OTHER

UNUSUAL FIRE AND EXPLOSION HAZARDS

Do not expose to spark or open flame.

Section V—HEALTH HAZARD DATA

EFFECTS OF OVEREXPOSURE

COPPER METAL IS SLIGHTLY TOXIC. DUST IRRITATES NOSE AND TRACHEA. SYMPTOMS WITH VOMITING AND INFLAMMATION BY INHALATION OF DUST. METAL FUME FEVER. DERMATITIS BY EXPOSURE. EFFECT IS TEMPORARY. CHRONIC TOXICITY IS CONFINED TO THOSE PERSONS SUFFERING FROM WILSON'S DISEASE.

EMERGENCY AND FIRST AID PROCEDURES

REMOVE FROM EXPOSURE IMMEDIATELY AND ALLOW TO REST.

Section VI—REACTIVITY DATA

STABILITY DUNSTABLE SYSTABLE

Excess heat CONDITIONS TO AVOID

INCOMPATABILITY (Materials to avoid) OXIDIZING ACIDS AND OTHER COPPER REACTIVE AGENTS HAZARDOUS DECOMPOSITION PRODUCTS

MINERAL ACID DECOMPOSITION YIELDS HYDROGEN AND TOXIC COPPER COMPOUNDS.

HAZARDOUS POLYMERIZATION THAY OCCUR SWILL NOT OCCUR

Section VII—SPILL OR LEAK PROCEDURES

STEPS TO BE TAKEN IN CASE MATERIAL IS RELEASED OR SPILLED SWEEP GENTLY TO AVOID DUST CLOUD FORMATION. WEAR SAFETY GOGGLES WITH SIDE SHIELDS, DUST MASK, AND GLOVES.

WASTE DISPOSAL METHOD

DISPOSE OF IN ACCORDANCE WITH LOCAL, STATE, AND FEDERAL REGULATIONS.

Section VIII—SPECIAL PROTECTION INFORMATION

RESPIRATORY PROTECTION NIOSH/MSHA approved dust mask.

USE ONLY IN OPEN, VENTILATED AREAS.

VENTILATION SUFFICIENT VENTILATION, IN VOLUME AND PATTERN, SHOULD BE PROVIDED TO KEEP AIR CONTAMINATION BELOW CURRENT APPLICABLE OSHA PERMISSIBLE LIMITS.

PROTECTIVE GLOVES REQUIRED FOR THOSE WITH

OTHER PROTECTIVE EQUIPMENT

EYE PROTECTION EXTREME SENSITIVITY COVERALLS, PROTECTIVE CREAM ON EXPOSED SKIN

WEAR SAFETY GOGGLES WITH SIDE SHIELDS

SURFACES

Section IX—SPECIAL PRECAUTIONS

PRECAUTIONS TO BE TAKEN IN HANDLING AND STORING

OTHER PRECAUTIONS

DO NOT TAKE INTERNALLY

11. 14 6 3